



LCS50



TERMINAL SCREW ASSIGNMENT

- # 1,2 : AC INPUT
- # 3 : FG
- # 4 : DC OUTPUT -V
- # 5 : DC OUTPUT +V



UNIT : mm  
Tolerance : +/-1.0mm